The state of the s

5

10

ABSTRACT

A method of manufacturing a three-dimensional mounted assembly includes steps of disposing a plurality of electronic parts on a mold, providing a plurality of interconnections on the mold by adhering them, sealing the electronic parts and the interconnections with a molding material, processing the surface shape of the molding material by the mold three-dimensionally, curing the molding material, and removing the mold from the molding material.